


MAGNITUDE 7.8 EARTHQUAKE

Saranggani and Davao Occidental



PHASE 1: RELIEF

Bringing help. Sharing compassion. Saving lives.
TOGETHER, WE CAN RISE AND REBUILD.



7.8 EARTHQUAKE RESPONSE

Saranggani and Davao Occidental

PHASE 1 – RELIEF OPERATION



Food Packs

1,220



Families

712



Pastors

35



Churches

32



Trips

3



Volunteers

Personnel 20
Vehicles 5

TOTAL FUND USED



Food Packs

₱ 287,668.00



Mobilization

₱ 16,860.31



Volunteers

₱ 13,041.00

TOTAL

₱ 317,569.31

PHASE 2 – REBUILDING IS NOW ONGOING.

MAGNITUDE 7.8 EARTHQUAKE

Saranggani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Saranggani and Davao Occidental.



PHASE 2: REBUILDING

Restoring our church. Restoring hope.

TOGETHER, WE CAN RISE AND REBUILD.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



CROSSING TAGAYTAY CBAP CHURCH

**Address:**

Crossing Tagaytay, Rio Del Pilar,
Glan, Sarangani

**Pastor:**

Ptr. Benedicto Wata Sr.

**Member Families:**

17 Families

**Damage Classification:**

TOTAL COLLAPSE

**DESCRIPTION**

Crossing Tagaytay CBAP Church sustained one of the most devastating levels of damage among the affected churches in the earthquake. The collapse of its foundation, walls, and roof has rendered the structure beyond repair, requiring a complete rebuilding effort.

Despite the loss of their sanctuary, the congregation remains steadfast in faith and committed to continuing their ministry while praying and working toward the restoration of their church home.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KILAYA CBAP CHURCH

**Address:**

Kilaya, Jose Abad Santos,
Davao Occidental

**Pastor:**

Ptr. Benir Mongkil

**Families:**

10 Families

**Damage Classification:**

TOTAL COLLAPSE

**DESCRIPTION**

Kilaya CBAP Church sustained total destruction during the Magnitude 7.8 earthquake that struck Davao Occidental and Sarangani in June 2026. The violent ground shaking caused the complete collapse of the sanctuary, leaving only portions of a masonry wall standing while the remainder of the structure crumbled into rubble.

The church is no longer safe for occupancy and requires complete reconstruction.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KAPLOBAY BAPTIST CHURCH



Address:

Sitio Kaplobay, Butulan,
Jose Abad Santos,
Davao Occidental



Pastor:

Ptr. Darvin Mariano



Member Families:

15 Families



Damage Classification:

PARTIAL MAJOR



DESCRIPTION

Kaplobay Baptist Church sustained partial major damage during the 7.8 magnitude earthquake. The structure experienced significant damage to its foundation, pillars, and walls. Debris and structural displacement were observed in several areas.

While the building is still partially standing and may be used with caution for the meantime, extensive repairs and strengthening are needed to ensure the safety of the congregation.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KALBAY TLV CHURCH



Address:

Kalbay, Jose Abad Santos,
Davao Occidental



Pastor:

Ptr. Remy Mongkil



Families:

18 Families



Damage Classification:

MAJOR PARTIAL



DESCRIPTION

Kalbay TLV Church sustained major partial damage during the 7.8 magnitude earthquake. The structure suffered significant damage to its walls, pillars, and foundations. Several concrete blocks collapsed, and portions of the building are unsafe for full use.

While part of the church is still standing and can be used with caution, urgent repairs and structural reinforcement are needed to ensure the safety of the congregation and continue ministry effectively.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KADUPANG CBAP CHURCH

**Location:**

Kadupang, Quiapo,
Jose Abad Santos,
Davao Occidental

**Pastor:**

Ptr. Nelson Bandojo Jr.

**Congregation:**

23 Member Families

**Damage Classification:**

PARTIAL MAJOR DAMAGE

**DESCRIPTION**

Kadupang CBAP Church sustained partial major structural damage during the Magnitude 7.8 earthquake that struck Southern Mindanao on June 8, 2026. While the timber superstructure and roofing system largely remained standing, the earthquake caused severe failure of the stone masonry foundation, extensive cracking of the concrete flooring, and displacement of structural components supporting the sanctuary.



MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KIDAMAN TLV CHURCH



Church Name:

Kidaman TLV Church

Address:

Kidaman, Jose Abad Santos,
Davao Occidental



Pastor:

Ptr. Recky Lawe F



Families:

20 Families



Damage Classification:

PARTIAL MAJOR DAMAGE



DESCRIPTION

The church building sustained partial major damage during the Magnitude 7.8 earthquake that struck Southern Mindanao on June 8, 2026. The whole building is leaning to the left, causing structural instability and posing a safety risk to the congregation.



MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



CROSSING PACO CBAP CHURCH



Address:

Crossing Paco, Laguimit,
Glan, Sarangani



Pastor:

Roatation



Families:

12 Families



Damage Classification:

PARTIAL MAJOR



DESCRIPTION

Crossing Paco CBAP Church sustained major partial damage during the Magnitude 7.8 earthquake that affected Sarangani and nearby provinces. The earthquake caused extensive cracking of the reinforced concrete walls, separation of masonry from the structural frame, and damage to the foundation and exterior walls. Although the roof remains largely intact, the structural integrity of the sanctuary has been compromised, making continued occupancy unsafe without substantial repairs.

The congregation has temporarily continued worship in an alternative and safer structure while awaiting rehabilitation of the church building.

MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



KITUMBOD CBAP CHURCH



Location:

Kitumbod, San Isidro,
Jose Abad Santos, Davao Occidental



Pastor:

Ptr. Reneboy Binangon



Congregation:

51 Member Families



Damage Classification:

MAJOR PARTIAL DAMAGE



DESCRIPTION

Kitumbod CBAP Church sustained major partial damage during the 7.8 magnitude earthquake. The structure experienced significant damage to its ceilings, walls, roof, and supporting posts.

While the building is still partially standing and is currently being used for services, repairs and strengthening are essential to ensure the safety and continued ministry of the congregation.



MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



AKBAANG CBAP CHURCH

**Location:**

Akbaang, Molmol,
Jose Abad Santos,
Davao Occidental

**Pastor:**

Ptr. Gino Estoon

**Families:**

23 Member Families

**Damage Classification:**

PARTIAL MAJOR DAMAGE

**DESCRIPTION**

Akbaang CBAP Church sustained partial major damage during the Magnitude 7.8 earthquake that struck Southern Mindanao on June 8, 2026. The whole building is leaning to the left, causing structural instability and posing a safety risk to the congregation. Cracks were observed on the foundation and flooring. Immediate repair and stabilization are needed to prevent further damage and ensure the safety of the congregation.



MAGNITUDE 7.8 EARTHQUAKE

Sarangani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Sarangani and Davao Occidental.



MAYBIO KIANAW CHURCH



ADDRESS:

Akbaang, Molmol,
Jose Abad Santos,
Davao Occidental



PASTOR:

Ptr. Nelson Dampa



FAMILIES:

14 Families



DAMAGE:

WHOLE STRUCTURE IS LEANING



DESCRIPTION

Maybio Kianaw Church sustained severe damage during the Magnitude 7.8 earthquake that struck Southern Mindanao on June 8, 2026. The whole structure is leaning to one side, showing signs of foundation failure and instability. Immediate attention is needed to ensure the safety of the congregation and prevent further collapse.



MAGNITUDE 7.8 EARTHQUAKE

Saranggani and Davao Occidental

A powerful 7.8 magnitude earthquake severely impacted communities, homes, and places of worship across Saranggani and Davao Occidental.



MISSION CENTER:
KALINAW SA BAGONG PAG-ASA CENTER



ADDRESS:
Tinoto, Maasim,
Saranggani



MISSIONARY:
Sis Rexie Altamirano



FAMILIES:
77 Contact Families



DAMAGE CLASSIFICATION:
MINOR DAMAGE



DESCRIPTION

Kalinaw sa Bagong Pag-Asa Center sustained minor damage during the Magnitude 7.8 earthquake that struck Southern Mindanao on June 8, 2026. The building experienced some structural cracks and falling debris, but remains safe for continued use and ministry.

